

Block by Block Recommendations | Negley Ave





LEFI: Signage for All Walk Pedestrian Phase located at 4 corners of Negley & Centre intersection

Block by Block Recommendations | Euclid Ave to Trade St




Intersection	Existing Safety Issues	Safety Recommendations (Reference #)
Centre & Euclid	 8 vehicular crash with no pedestrian incident Unsafe crosswalks Lane control is an issue Part of Penn Circle conversion project 	 Place bike lane behind bus stop for added bike pedestrian protection Add Hi Viz crosswalk
Centre & Beatty	 11 vehicular and 1 pedestrian crashes Crosswalks need replaced Traffic signal and No Turn on Red signage need replaced 	 Hi Viz crosswalk Install bumpout and upgrade curb ramps on north east corner Upgrade signal
Centre & Trade	• 1 vehicular crash with no pedestrian incident	6. Install concrete bumpout and improve intersection sight distance
Between Euclid and Highland	• Lane numbers and arrangement is inconsistent causing driver confusion	 Reconfigure pavement markings to ensure consistency in lane number, bike lanes and a shared bike lane/bus stop



Crash data is from 2017-2021 collected from Pennsylvania Crash Information Tool (PCIT).

Block by Block Recommendations | Highland Ave to Kirkwood St



Intersection	Existing Safety Issues	Safety Recommendations (Reference #)
Centre & Highland	 4 vehicular and 4 pedestrian crashes Poor pedestrian visibility Intersection skewed impairing left turn visibility 	 Hi Viz crosswalk Install left turn signals Remove turn lane, install bumpout to improve pedestrian visibility with shortened crosswalk, and create 2 additional parking spaces
Centre & Annie Place		4. Hi Viz crosswalk
Centre & Penn	 14 vehicular and 3 pedestrian crashes Unsafe pedestrian crossing Traffic backs up through intersection 	 Eliminate right turn lane and shorten crosswalks Move cross walk closer to intersection and remove plants that impact visibility Provide a mountable concrete island to separate traffic Re-time signal with enhanced pedestrian safety treatment (Leading Thru Interval treatment)
Centre & Kirkwood	• 2 vehicular and 1 pedestrian crashes	No proposed improvements


Key New Signal ADA Ramp Bus Shelter Bike Lane Bike Lane Bike Lane Bike Lane Bike Lane

Crash data is from 2017-2021 collected from Pennsylvania Crash Information Tool (PCIT)

Block by Block Recommendations | Broad St to Station St



Intersection	Existing Safety Issues	Safety Recommendations (Reference #)
Centre & Broad	 9 vehicular crashes with no pedestrian incident Crosswalk markings hard to see Traffic backs up through intersection due to adjacent signals 	 Hi Viz crosswalk Re-time/sync signal to the signals at Penn Ave and Centre Ave and the Target entrance
Centre & Harvard	• 1 vehicular crash with no pedestrian incident	No proposed improvement
Centre & Station	 1 vehicular crash with no pedestrian incident Inadequate bike connection to Station St 	 Improve bike connection between Station St and existing bike lanes on Centre Ave Hi Viz crosswalks improve pedestrian visibility as part of Penn Circle Conversion




Crash data is from 2017-2021 collected from Pennsylvania Crash Information Tool (PCIT)

Block by Block Recommendations | Kalida Dr to East Liberty Boulevard



Intersection	Existing Safety Issues	Safety Recommendations (Reference #)
Centre & Kalida	No crash incidents	No proposed improvements
Centre & Rodman	No crash incidents	No proposed improvement
Centre & East Liberty Blvd	 12 vehicular crashes with no pedestrian incident No advanced left turn phases Bus stop and bike lane conflicts 	 Upgrade signals Provide curb bumpouts. Route bike lanes behind bus stop. Place bus shelter on bumpout.



Crash data is from 2017-2021 collected from Pennsylvania Crash Information Tool (PCIT)